## BUILDING SAFETY CERTIFICATE

No	Dated: 08:06:2023
	The second control of

Certified that the existing building BTC Public School Puthencruz (name of the building or premises) at Puthencruz. P.O., Ernakulam Dist, Kerala (address) comprised of two basement(s) and two upper floors owned/occupied by BTC Public School Puthencruz (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Local Self Government (Vadavucode - Puthencruz Grama in the presence of Sr. Yohanna, Manager BTC Public School Puthencruz (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes X (X/ XII) with effect from 01-06-2023 for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

1.

2.

3

4

Issued on 08.06.2023, at by

\* Strike out whichever is not applicable.

Signature with Seal:

Name: Sanhpsh.

Designation:

Name & Address of Department/ Office

(Assistant Engineer & above officer of concerned Govt. Department on

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

Puthencru2

PUTHENCRUZ - 682 308

## TO BE FILLED BY THE INSPECTING OFFICER

(Junior Engineer)

Name of the Officer

Santhosh. K.N.

Name of School

B.T.C. Public School Puthencruz

3 Location with Edn. Dist. I Sub Dist.

Putheneny Alwa Kolenchery.

Classification of the building and size (basis for classification see Annexure 1)

Sheet Separately attached

Permanent (single or multi storeyed)

2 BLOCKB

Semi pormanent

III) Temporary shod

Period for which the contificate is issued

2023.24

Nature of defens, if any

Loundation and basement

R.C.C

Dispulsation from

brunt and agodows

masonary

Woods was wrought and put up

Escut

ii) Mint (Can be etc.)

Flooring

Coxami flooring

Any Major defects noticed which will reader the building unsafe in any manner

Whather mentenance works have been done properly

Whether the structure is sound or not for conducting dasses

401

- The stability of the structure should be examined also with reference to location, attitude intensity of wind exposure flood etc.
- Any additional observations if docmed necessary) for the certificate may be furnished separately with the certificate.

Certified that the School was inspected by me on 22:05-2023 be fit I will to conduct for the period 2022:23 under normal weather

Signature

22.05-2023

Designation:

- 682 308

VADAVUKODU-PUTHENCRUZ

C. PUBLIC SCHOOL

Puthencruz

ATHOLIC

SGD Section

## BLOCK A

GROUND FLOOR	LENGTH	BREADTH	HEIGHT		
East West	55.25	09.01	3.5	Visitors room	1
North south East side	49.25	09.01	3.8	Reading room	1
North South West side	52.12	09.01	3.8	Office rooms	2
Porch South Sheet	06.00	04.52	3.6	Staff rooms	2
Porch North	03.47	04.00	3.8	Conference rooms	2
THE THE PARTY OF T			260	Class rooms	12
				Toilet blocks	2
FIRST FLOOR			,		
East West	55.25	09.01	3.8	Staff rooms	1
North South West side	49.28	09.01	3.8	Class rooms	14
Room over porch	03:47	04.00	3.8	Toilet Blocks	2
North South East side	49.28	09.01	3.8	Class room	6
SECOND FLOOR					
East West	55.25	09.01	3.8	Class rooms	8
North South West side	52.12	09.01	3.8	Class rooms	7
North South East side	49.28	09.01	3.8	Class rooms	7

## BLOCK B .

GROUND FLOOR	LENGTH	BREADTH	HEIGHT		
East West	55.25	09.01	3.5	Visitors room	1
				Class rooms	18
				Office room	1
				Staff room	1
				Electrical room	1
				Store room	1
				Toilet blocks	2



ASSISTANT ENGINEER
LOCAL SELF GOVERNMENT VADAVUKODU-PUTHENCRUZ



PRINCIPAL
BTC Public School
Puthencruz - 682 308

