

FITNESS CERTIFICATE

(To be filled by the Asst. Engineer)

1. Name of the Officer : SANTHOSH K.A.
2. Name of the School : B.T.C. Public School, Puthencruz.
3. Location with name of Edn. Dist./ Sub Dist. : Puthencruz / Aluva / Kolencherry.
4. Classification of buildings as specified in column 4 of the application for fitness certificate, and size : Sheet Separately Attached.
A-Block - Gr. Floor Full
B-Block - F. Floor Part.
2022-2023
5. Period for which certificate is issued : 2022-2023
6. Nature of defects if any : Nil
- a) Foundation and basement : R.C.C
- b) Superstructure : Masonry
- c) Doors and windows : Country Wood
- d) Wood work wrought and put up : Country Wood.
- e) Roof : R.C.C.
- f) Flooring : Ceramic Flooring
- g) Miscellaneous (cracks etc) : -
7. Any major defects noticed which will render the building unsafe in any manner : No
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Yes.

- Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that school building was inspected by me on 23-05-2022

..... and found / fit/ unfit to conduct classes for the period of/ academic year

2022-2023.
weather condition.

..... for the reasons cited above, under normal

Place Puthencruz.



Signature

Designation

PRINCIPAL
BTC Public School

ASSISTANT ENGINEER
LOCAL SELF GOVERNMENT DEPARTMENT
VADAVUKODU-PUTHENCRUZ

MANAGER

B. T. C. PUBLIC SCHOOL
PUTHENCRUZ - 682 306

BLOCK 'A						
	Length (m)	Breadth (m)	Height (m)			
GROUND FLOOR						
East West	55.25	9.01	3.8	Visitors Room		1
North South East Side	49.28	9.01	3.8	Reading Room		1
North South West Side	52.12	9.01	3.8	Office Rooms		2
Porch South Sheet	6.00	4.52	3.6	Staff Rooms		2
Porch North	3.47	4.00	3.8	Conference Rooms		2
				Class Rooms		12
				Toilet Blocks		2
FIRST FLOOR						
East West	55.25	9.01	3.8	Staff Rooms		1
North South West Side	49.28	9.01	3.8	Class Rooms		14
Room Over Porch	3.47	4.00	3.8	Toilet Blocks		1



[Signature]
25/9/22
ASSISTANT ENGINEER
LOCAL SELF GOVERNMENT DEPARTMENT
VADAVUKODU-PUTHENCRUZ



[Signature]
PRINCIPAL
BTC Public School
Puthencruz - 682 308

[Signature]
MANAGER
B. T. C. PUBLIC SCHOOL
PUTHENCRUZ - 682 308

FITNESS CERTIFICATE

BLOCK B	Length (m)	Breadth (m)	Height (m)		
GROUND FLOOR					
East West	78	26.1	3.8	Visitors Room	1
			3.8	Class Rooms	18
			3.8	Office Rooms	1
			3.6	Staff Rooms	1
			3.8	Electrical Room	1
				Store Room	1
				Toilet Blocks	2



[Signature]
23/9/22.

ASSISTANT ENGINEER
LOCAL SELF GOVERNMENT DEPARTMENT
VADAVUKODU-PUTHENCRUZ



[Signature]
PRINCIPAL
BTC Public School
Puthencruz - 682 308

[Signature]
MANAGER
B. T. C. PUBLIC SCHOOL
PUTHENCRUZ - 682 308

No/

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Exe. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- Name of the School** : BTC Public School, Puthencruz
1. Name of the Officer : JOSE M. P.
Edn. District: Aluva
Edn. sub. District: Kolenchery.
2. Location
3. Period for which the certificate is issued : 2022-23.
4. Types of building : RCC Framed Structure
5. Nature of defect if any
- a) Foundation and basement :
b) Superstructure :
c) Doors and windows :
d) Wood work wrought and put up :
e) Roof :
f) Flooring :
g) Miscellaneous (Cracks if any) :
- F. Floor : $49.28 \times 9.01 \times 3.80$ (6 class ro
S. Floor : $55.25 \times 9.01 \times 3.80$ (8 class ro
 : $52.12 \times 9.01 \times 3.80$ (7 class ro
 : $49.28 \times 9.01 \times 3.80$ (7 class ro
- No defects.
6. Any Major defects notices which will render the building unsafe in any manner : No.
7. Whether maintenance works have been done properly : Yes.
8. Whether the structure is sound or not for conducting classes : Structure is sound under normal weather condition.

- Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 27. 07. 2022
and found to be fit / ~~unfit~~ to conduct classes for the period 2022-23
for the reason stated above (First Fitness)

Place: Kolenchery.....

Date: 17. 08. 2022.....



PRINCIPAL
BTC Public School
Puthencruz - 682 308



JOSE M.P.
Assistant Executive Engineer
LSGD Sub Division
Vadavucode B.P.
Kolenchery P.O. - 682 308

MANAGER
B. T. C. PUBLIC SCHOOL
PUTHENCRUZ - 682 308