

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 17/5/2024

It is certified that the existing building B.T.C. Public School, Puthencruz (name of the building or premises) at Puthencruz P.O, Ernakulam Dist, Kerala

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
	<u>A</u>	<u>B</u>				
No. of Floor(s) in the Block	<u>3</u>	<u>1</u>				

The building is owned/occupied by B.T.C. Public School, Puthencruz..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Local Self Govt. Puthencruz (Name of panchayath Department/ Govt.) on 17/5/2024.....(date of inspection) in the presence of St. Yohanna, Manager B.T.C. Public School, Puthencruz and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 17/5/2024 for a period of one..... years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 17/05/2024 at 1.30 PM by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : Sanjay K.R.

Designation : ASSISTANT ENGINEER

Name & Address of Department/ Office : LOCAL SELF GOVERNMENT DEPARTMENT PUTHENCRUZ



FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

1. Name of the Officer Santhosh K.N
2. Name of the School BTC Public School, Puthencruz
3. Location with name of Education District/ Sub. District Puthencruz/Aluva/Kolenchery
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Block A :- G.F, F.F & S.F } Sheet
Block B :- G.F } separately
attached

5. Period for which the certificate is issued 2024-25
6. Nature of defects, if any
a) Foundation and basement Nil
b) Superstructure R.C.C
c) Doors and Windows Masonry
d) Wood work wrought and put up Country wood
e) Roof Country wood
f) Flooring R.C.C
g) Miscellaneous (Cracks, etc.) Ceramic flooring
7. Any major defects noticed which will render the building unsafe in any manner No
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Sound for conducting classes.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 16/5/2024 and found to be fit / unfit to conduct classes, for the period 2024-25 under normal for the reasons stated above. weather conditions.

Place: Puthencruz
Date: 17/5/2024



ASSISTANT ENGINEER
LOCAL SELF GOVERNMENT DEPARTMENT
VADAVUKODU-PUTHENCRUZ

BLOCK A

GROUND FLOOR	LENGTH	BREADTH	HEIGHT		
East West	55.25	9.01	3.70	Store, Visitors room, Office, Principle room, Staff room-2, Conference room	
North South East side	49.25	9.01	3.70	Class rooms	6
				Toilet Block	1
North South West side	52.12	9.01	3.70	Class rooms	6
				Toilet Block	1
Porch South Sheet	6.00	4.52	3.60	Porch	1
Porch North	3.47	4.00	3.80		
FIRST FLOOR					
East West	55.25	9.01	3.70	Class rooms	8
North South West side	52.12	9.01	3.70	Class rooms	6
				Toilet Block	1
Room over porch	3.47	4.00	3.70	Prayer room	1
North South East side	49.28	9.01	3.70	Class rooms	6
				Toilet Block	1
SECOND FLOOR					
East West	55.25	9.01	3.70	Class rooms	8
North South West side	52.12	9.01	3.70	Class rooms	6
				Toilet Block	1
North South East side	49.28	9.01	3.70	Class rooms	6
				Toilet Block	1

BLOCK B

GROUND FLOOR	LENGTH	BREADTH	HEIGHT		
East West	78.55	26.01	3.52	Visitors room	1
				Class rooms	18
				Office room	1
				Staff room	1
				Electrical room	1
				Store room	1
				Toilet Blocks	2




ASSISTANT ENGINEER
LOCAL SELF GOVERNMENT DEPARTMENT
VADAVUKODU-PUTHENCRUZ