

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated: 12/5/2025

It is certified that the existing building B.T.C. Public School ..... (name of the building or premises) at Puthencruz P.O, Esnakulam Dist, Kerala .....

..... (address) is having block(s)/Floor(s) as per details below:

| Detail of Block(s) in school | Block (1) A | Block (2) B | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|-------------|-------------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | 3           | 1           |           |           |           |           |

The building is owned/occupied by B.T.C. PUBLIC SCHOOL, PUTHENCRUZ (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Local Self Govt. Vadavukodu, Puthencruz (Name of Department/ Govt.) on 12/5/2025 ..... (date of inspection) in the presence of Manager, B.T.C. Public School, Puthencruz (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 17/5/2025 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 12/5/2025 at 1.00 PM by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



Signature with Seal: [Signature]

Name: Srinthosh K.N

Designation: ASSISTANT ENGINEER

Name & Address of Department Office: LOCAL SELF GOVERNMENT DEPARTMENT VADAVUKODU-PUTHENCRUZ

## **FITNESS CERTIFICATE**

To be filled by the Inspecting Officer (Asst. Engineer)

(Re.G.O Ms.20/70/PWD Dt.23-01-1970)

- 1.Name of the Officer : Santhosh K.N
- 2.Name of the School : BTC PUBLIC SCHOOL , Puthencruz
- 3.Location with name of Education District / Sub.District : Puthencruz/Aluva/Kolenchery
4. Classification of Building as specified in column 4 of  
the application for fitness certificate and size :
- 1)Block A – G.F , F.F & S.F }  
2) Block B – G.F } Sheet separately attached
5. Period for which the certificate is issued : 2025-26 Academic Year
6. Nature of defects , if any : Nil
- a) Foundation and Basement : R.C.C
- b) Superstructure : Masonry
- c) Doors and Windows : Country wood
- d) Wood work wrought and put up : Country wood
- e) Roof : R.C.C
- f) Flooring : Ceramic Flooring
- g) Miscellaneous ( Cracks etc) : No
7. Any major defects noticed which will render the  
building unsafe in any manner : No
8. Whether Maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Yes sound for conducting classes

Note : 1 The stability of the structure should be examined also with reference to location , attitude, intensity of wind , exposure of flood etc.

2.Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

**CERTIFICATE**

Certified that the school building was inspected by me on...16/5/2025...and found to be fit to conduct classes for the period 2025-26 Academic Year under normal wind & Weather Conditions .

Place : Puthencruz

Date ...16/5/2025...

( Seal)



Assistant Engineer



**ASSISTANT ENGINEER  
LOCAL SELF GOVERNMENT DEPARTMENT  
VADAVUKODU-PUTHE**

**BLOCK – A**

**CLASSIFICATION OF THE BUILDING & SIZE**

| GROUND FLOOR                   | LENGTH | BREADTH | HEIGHT | NAME   | No.OF ROOMS |
|--------------------------------|--------|---------|--------|--|-------------|
| East West                      | 55.25  | 9.01    | 3.70   | Store , Visitors room , Office, Principal room , Staff room -2 , Conference room | 6           |
| North South East side          | 49.25  | 9.01    | 3.70   | Class rooms  | 6           |
|                                |        |         |        | Toilet Block   | 1           |
| North South West side          | 52.12  | 9.01    | 3.70   | Class rooms  | 6           |
|                                |        |         |        | Toilet Block   | 1           |
| Porch South Sheet              | 6.00   | 4.52    | 3.60   | Porch  | 1           |
| Porch North                    | 3.47   | 4.00    | 3.80   |  |             |
| <b>FIRST FLOOR</b>             |        |         |        |  |             |
| East West                      | 55.25  | 9.01    | 3.70   | Class rooms  | 8           |
| North South West side          | 52.12  | 9.01    | 3.70   | Class rooms  | 6           |
|                                |        |         |        | Toilet Block   | 1           |
| Room over porch                | 3.47   | 4.00    | 3.70   | Prayer room  | 1           |
| North South East side          | 49.28  | 9.01    | 3.70   | Class rooms  | 6           |
|                                |        |         |        | Toilet Block   | 1           |
| <b>SECOND FLOOR</b>            |        |         |        |  |             |
| East West                      | 55.25  | 9.01    | 3.70   | Class rooms  | 8           |
| North South West side          | 52.12  | 9.01    | 3.70   | Class rooms  | 6           |
|                                |        |         |        | Toilet Block   | 1           |
| North South East side          | 49.28  | 9.01    | 3.70   | Class rooms  | 6           |
|                                |        |         |        | Toilet Block   | 1           |
| <b>BLOCK B ( Ground Floor)</b> |        |         |        |  |             |
| East West                      | 78.55  | 26.01   | 3.52   | Visitors room  | 1           |
|                                |        |         |        | Class rooms  | 18          |

|  |  |  |  |                 |   |
|--|--|--|--|-----------------|---|
|  |  |  |  | Office room     | 1 |
|  |  |  |  | Staff room      | 1 |
|  |  |  |  | Electrical room | 1 |
|  |  |  |  | Store room      | 1 |
|  |  |  |  | Toilet Blocks   | 2 |



**ASSISTANT ENGINEER  
LOCAL SELF GOVERNMENT DEPARTMENT  
VADAVUKODU-PUTHENCRUZ**